USE PERMIT

FOR

40 East San Martin, San Martin CA. FILE NO. 10809-71-30-16P



AERIAL




TABLE OF CONTEN S

- SITE PLAN
- 2.1 DETAIL AND SPECIFICATION
 3.0-3.1 EXISTING GRADING AND DRAINAGE PLAN
- LANDSCAPE PLAN **EXISTING FLOOR PLAN AND ELEVATIONS**

4.0 6.0

PROJECT DESCRIP TION & INFORMATION

825-02-137

PROJECT ADDRESS: ASSESSOR'S PARCEL NUMBER

ZONING DESIGNATION

NET SITE AREA GROSS SITE AREA

PROPOSED USE

TRĀFFIC TRIP GENERATION:
9 Daily Trips

40 E SAN MARTIN, SAN MARTIN, CA LIGHT INDUSTRIAL +/-2.01 AC /- 2.01 AC

PROPOSAL FOR A TRUCK EQUIPMENT INSTALLATION FACILITY WITH INCIDENTAL SALES.

HOURS OF OPERATION WILL BE 9AM TO 5PM MONDAY THROUGH FRIDAY AND WEEKENDS BY SPECIAL APPOINTMENT

MAXIMUM CAPACITY OF 2 CUSTOMERS AND 5 STAFF PERSONS AT ANY ONE TIME ONSITE

NO MAJOR ALTERATIONS TO THE EXTERIOR OF THE EXISTING BUILDING ARE PROPOSED, PLEASE SEE ACCOMPANYING LETTER FOR MORE DETAIL

FINISHED VEHICLE PARKING AS SHOWN ON PLANS REFERS TO VEHICLES THAT HAD EQUIPMENT RACKS INSTALLED. WHICH IS THE PRIMARY BUSINESS AND USE PROPOSED FOR THE SITE.

DEVELOPMENT TE/

DEVELOPER/OWNERSINGH SURINDER / BALWINDER KAUR BADWAL
4339 VISTA PARK SAN JOSE, CA 95136


VER CONSULTANTS 1154 PARK AVE

LAND PLANNER & ENGINEER

OFFICE: (408) 834-7889 SAN JOSE CA. 95126

40 E SAN MARTIN, SAN MARTIN, CA **USE PERMIT** ITLE SHEET





			TRUCK SALES AND SERVICES	USE	
AD	10:	10:	2 PER VEHICLES WORK STATION 1 PER EMPLOYEE	PARKING RATIO REQUIREMENT	PARKING ANALYSIS
ADA PARKING PROVIDED	TOTAL PARKING PROVIDED	TOTAL PARKING REQUIRED	2 WORK STATIONS = 4 SPACES 5 EMPLOYEES=5 SPACES	PARKING SPACE REQUIREMENT	NALYSIS
_	9	9			

SEE SHEET 6.0 FOR EXISTING TREES AND PROPOSED TREE INFO

NOTE

CCCCCCC

REVISIONS

PROJECT DATA

EXISTING CIRCULATION ARROW OF UNFINISHED VEHICLES BUILDING SETBACK LINE (BSL) PROPERTY BOUNDARY EDGE OF PAVEMENT LEGEND RIGHT OF WAY (ROW) RAIL ROAD TRACK FIRE HYDRANT CENTER LINE LOT LINE FENCE PROPOSED Ţ,

CIRCULATION ARROW OF FINISHED VEHICLES

40 E SAN MARTIN, SAN MARTIN, CA SITE PLAN

USE PERMIT





1020 Ruff Drive San Jose, California 95110 Office (408) 377-9990 Fax (408) 492-1008 24 Hour Emergency Service

(408) 398-4990

SEPTIC TANK INSPECTION REPORT

INVOICE NO: 34738 DATE: 04-18-16 JOB SITE: 40 E. San Martin Auc. San Martin, G. 95046 Owner: Surrinder Singh BUYERS: N/A PHONE: REALTY COMPANY: FAX: ADDRESS: CUSTOMER HAS CESSPOOL () SUMP () SEPTIC TANK CONCRETE WITH WOOD () IS UNIT ALL CONCRETE (A) TANK ALL WOOD (IF TANK HAS WOOD TOP, HOW MANY LAYERS: N ONE () TWO () CONDITION OF WOOD: N/ GOOD () FAIR () ROTTEN () INLET /OUTLET (ELBOWS): GOOD IF BAD/BROKEN WHICH: INLET () OUTLET () ,200 ESTIMATED GALLONS: DOES UNIT NEED PUMPING: YES () YES () NO ST DATE PUMPED: DID ABLE PUMP TANK: DOES LIQUID LEVEL INDICATE LEECHING APPEARS TO BE IN WORKING ORDER: YES () FAILED () OR QUESTIONABLE () ANY EVIDENCE OF SEWAGE OR SEWER WATER BREAKING OUT OF GROUND: YES () NO Front of Building V MAP LOCATION OF SEPTIC TANK:

Scotic fank is in washing condition. Leach field passed 30 minute water foot. As of 04-18-16 at 9:00 A-M. Scotic fank passes inspection.

REPORT COMPLETED BY: July Better and

Underground Construction: Septic - Sewer - Storm - Water - Excavated & Installed - Repaired - Pumped - Inspected - Inspected - Plumbing Sewer & Drain: Line Cleaning - Rodding - Repaired - Replaced - Residential & Commercial Vacuum: Septic - Sewer Storm - Grease Traps/Interceptors - Hydro Flushing: Sewer - Storm - Maintenance - Public Works - Overflow & Spill Response Main Line Stoppages - Pipeline Video Inspection: Pipeline Inspection - Line Locating - Detailed Reports - Complete 24 Hr. Emergency Service www.ablesewer.com - www.abledeckandfence.com - www.valleyconcrete.com

SEPTIC TANK INSPECTION

San Martin County Water District

Serving the San Martin Area East of Monterey Road
P.O. BOX 120, SAN MARTIN, CALIFORNIA 95046

March 8, 2016

RE: APN# 825-02-137 40 East San Martin Ave San Martin, CA 95046

To Whom It May Concern:

San Martin County Water District (SMCWD) currently supplies water service to the above referenced property and will continue to serve the new owners.

The referenced property has a 1" service line connected to an 6" water main located on the edge of pavement across the street. The main building on the property has a 0.75" water meter. The District has no opinion as to the flow available to the building, but a contractor can easily perform a flow test to ensure that it meets your requirements. The property is also serviced by another 1" service line connected to another 0.75" water meter located on the northwest corner of South and Depot Streets. The service valve for this second meter is closed and locked-out at the previous owner's request because of a leak in the customer's yard piping. We will unlock at the new owner's request.

A standard fire hydrant is located across the street on the southeast corner of East San Martin Ave. and Depot St. An additional standard hydrant is located at the northeast corner of Depot St. and Spring Ave. across the street from the southern portion of the above referenced property lot.

Each of these hydrants is supplied in two directions by a 6" water main loop which is supplied by the 8" water main on Llagas Avenue, which is supplied by the 12" water main on East San Martin Ave. Static pressure at this location averages 65 psig. Water is supplied by a well and pressure system located on Sycamore Avenue and capable of producing up to 2,000 GPM at the source.

Due to friction loss through the distribution piping, flow available at each of these hydrant locations is estimated to be between 1500 - 1600 GPM @ 20 psig residual. The above flows are for individual use, NOT simultaneous use. Peak total flow for simultaneous use would be approximately1800 GPM @ 20 psig residual.

Please note that San Martin County Water District is only responsible for domestic water use flows and is not required to supply any particular fire flow.


Please feel free to call if you have any questions.

Sincerely yo

Peter J. Forest, Manager

San Martin County Water District

WATER DISTRICT LETTER



STALL SIGN


PROJECT: 2016.552
DRAWN: YC
DESIGN: VR
SCALE:
DATE: APRIL 27, 2017
© VER-CONSULTANTS INC

REVISIONS PROJECT DATA





USE PERMIT
DETAIL AND SPECIFICATION
40 E SAN MARTIN, SAN MARTIN, CA



















EXISTING GRADING AND DRAINAGI 40 E SAN MARTIN, SAN MARTIN **USE PERMIT** П

PROJECT DATA





Engine, trans, rear end oils, brake fluid, power steering fluid, greases

Haz waste recycling systems for oils & fluids

Depot


3 t

BUILDING

Cleaning, preparation products, solvents, thinners, grease removers, stain removers, adhesive removers, polishing pastes

Cutting & welding PPE XI


Vehicle Fahricaion & Maintenance Area





USE PERMIT


EXISTING FLOOR PLAN & ELEVATIONS 40 E SAN MARTIN, SAN MARTIN, CA


SHEET NUMBER











PRELIMINARY LANDSCAPE PLAN

USE PERMIT

