

LEGEND

- FOUND 1" IRON 💢 JP JOINT POLE PIPE WITH NAIL AND X PP POWER POLE UNREADABLE TAG IN MONUMENT WELL X UP UTILITY POLE UNLESS OTHERWISE X TP TELEPHONE POLE
- O SET 5/8" REBAR WITH ĆAP LS 5571 ⊗ VALVE 🖒 HCP SYMBOL - SIGN ---- EASEMENT LINE
- ---- TIE LINE TRAFFIC ARROWS -ss- ug sewer line S SANITARY SEWER MANHOLE
- SD STORM DRAIN MANHOLE - G - UG GAS LINE © COMMUNICATION MANHOLE -PH- UG PHONE LINE PERC TEST
- ♦ FIRE HYDRANT -OH- OVERHEAD LINE © SEWER CLEANOUT E UTILITY BOX SURVEY CONTROL POINT

EM ELEC METER

MB MAILBOX

- GM GAS METER C LAMP POST WM WATER METER ------CHAIN LINK □→⊗ LIGHT POLE AND LIGHT -⊶ WIRE FENCE DROP INLET
- BUILDING

SURVEYOR'S STATEMENT

THIS MAP CORRECTLY REPRESENTS A SURVEY MADE BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE REQUIREMENTS OF THE LAND SURVEYORS ACT. THE BOUNDARY LINES SHOWN ON BASED ON A BOUNDARY SURVEY DONE BY WILSON LAND SURVEYS INC.

Kenno D. Wilso 12/20/2022

KENNETH D. WILSON LS 5571 DATE

BENCHMARK

ELEVATIONS FOR THIS SURVEY ARE BASED ON ELEVATION OF 500.00° AT CONTROL POINT #101.

GENERAL NOTES

1. TREE SIZES AND TYPES ARE APPROXIMATE AND SHOULD BE VERIFIED BY A CERTIFIED ARBORIST. 2. FINISH FLOOR ELEVATIONS ARE TAKEN AT DOOR THRESHOLDS. 3. BUILDING CORNERS WERE LOCATED AT FINISH

LOCATIONS (STUCCO, BLOCK OR WOOD AS IT EXISTS IN THE FIELD).

UNDERGROUND UTILITY NOTE

UNDERGROUND UTILITY LINES, IF SHOWN, DEPICT OUR ESTIMATION OF WHERE THE ACTUAL LINES MAY BE LOCATED. THE LINES WERE DETERMINED BY CONNECTING VISIBLE UTILITY APPURTENANCES AND ALSO BY USING PAINTED MARKINGS PLACED BY OTHERS. THE UNDERGROUND UTILITIES MAY OR MAY NOT BE AS DEPICTED ON THIS SURVEY. NO LIABILITY IS ACCEPTED FOR ANY DISCREPANCIES, OMISSIONS OR ERRORS WITH REGARD TO SAID UNDERGROUND UTILITY DEPICTIONS ON THIS SURVEY.

IF NO INDICATION OF SEWER LINES ARE SHOWN, THEN THERE WERE NO VISIBLE MARKINGS OR INDICATIONS OF ANY SEWER APPURTENANCES ON THE SITE. OTHER RECORDS MAY EXIST THAT PROVIDE EVIDENCE OF SEWER LATERAL LOCATIONS.


SETBACK LINES NOTE

BUILDING SETBACK LINES WERE NOT SHOWN ON THIS MAP (EVEN IF THEY ARE SHOWN ON THE ORIGINAL TRACT MAP). THE DESIGNER SHOULD CHECK WITH THE APPROPRIATE AUTHORITY TO DETERMINE BUILDING SETBACK LINES.

TITLE REPORT NOTE

A CURRENT TITLE REPORT WAS NOT AVAILABLE AT THE TIME OF THIS SURVEY. EASEMENTS MAY EXIST ON THIS PROPERTY WHICH ARE NOT SHOWN. A CURRENT TITLE REPORT IS REQUIRED IN ORDER TO DETERMINE THE EXISTENCE OF ANY EASEMENTS OF RECORD. THE BOUNDARY WAS DETERMINED FROM THE CURRENT VESTING DEED.

> Email: kenw@wilsonlandsurveys.com www.wilsonlandsurveys.com



TOPOGRAPHIC SURVEY

AS REQUESTED BY: JOHN CROSS

LEGAL DESCRIPTION: LOTS 9 AND 10, INTERURBAN PARK TRACT K M 21, CITY OF SAN JOSE, COUNTY OF SANTA CLARA, STATÉ OF CALIFORNIA

APN: 274-19-061

DATE: DECEMBER 2022

TE ADDRESS: 124 BOSTON AVE, SAN JOSE, CA 95128

JOB NUMBER PROJECT

NO. 5571